



Reinforced Concrete Silos Solutions for Maintenance, Rehabilitation, Strengthening



Why do Silos need Rehabilitation? The Key to Success

What are Silos?

Silos are large, thin-walled reinforced concrete shell structures with large diameter and height for storage of corn, wheat, grain, sugar, cement, coal.



Frequent Problems

- Large vertical and horizontal cracks
- Low concrete strength
- Spalling of concrete
- Construction joints
- Corrosion of re-bars
- Reduction of concrete cover for reinforcement

Reasons

- Concrete deterioration and abrasion (⇔ quality of concrete due to casting and/or curing)*
- Overstressing in re-bars
- (⇒ insufficient cover of re-bars)* Construction faults (⇒ inexact position of re-bars in formwork)*
- Design assumptions (⇒ pressure, dynamic and seismic loads)
- User errors
- (⇒ inappropriate manipulation) Environmental influences
- (\Rightarrow termal variations, rain, co₂, carbonation)
- * Silos are specially sensible to these problems because there are thin-walled structures twall = 20-30 cm, erected by slip- or climbingform techniques.









Alternative Solutions

\				¥
Downgrade the Capacity of Silos (with periodical inspection)		Rehabili		
				V
		The	Sika	syste
Concrete Repair and Protection: Sika System Solutions for concrete and SikaQuick® System (Cosmetic Rep Sika® MonoTop® System (Structur Sika® FerroGard® (Corrosion Inhill Sikaplan® (Membrane Systems) Sikagard® (Coating Systems)	l re-b pair) ral Re bitor)	ars epair))		
Sika is today the worldwide Key Leader & Playe	er in	the cond	crete re	habilitation





market field. For more information please contact the local Sika Company, which address you will find on the back side.

Case Studies

Albany, Western Australia



The Project

Units with 16 and 20 cells Diameter of a cell: 12m Height of a cell: 33m

The Problem

Large-vertical cracks inside of cell walls



Cells for strengthening

The Sika® Solution

- Injection of cracks with Sika System Solution
- Strengthening of cell walls on inside with:

₽	SikaWrap®-230 C	ca. 16'000m ²

Sikadur®-330 epoxy adhesive ca. 22'000kg

Sika Services AG

Corporate Construction CH-8048 Zürich Switzerland Phone +41 1 436 40 40 Fax +41 1 436 46 86 www.sika-construction.com

Silo Santiago de Chile, Chile



The ProjectUnit with 10 cellsDiameter of a cell:6mHeight of a cell:22m

The Problem

- The silo presented outside cracks in several directions mainly vertical
- Inadequate spacing of reinforcement
- Concrete joints
- Low concrete strength
- Inappropriate use of space between silos (filled with wheat), this factor caused eccentric loads between silos (horizontal loads)
- Industry unable to operate under this conditions



The Sika® Solution

- Prepare and clean surfaces and cracks
- Restore monolitism of the structure by epoxy injectioning of concrete substrate
- Externally strengthen silos with
 - ➡ SikaWrap®-230 C
 - Sikadur[®]-330 epoxy adhesive ca. 680kg
- Application of an UV protection
 - Sikagard®-550 W coating

Your local Sika Company

Our most current General Sales Conditions shall apply. Please consult the Product Data Sheet prior to any use and processing.





ca. 500m²