

SPECIFICATION SHEET NO: NW403

NEW WORK/REPAINT: NEW WORK – INTERIOR

SUBSTRATE: Wood

PAINT FINISH: Plascon Glatex 8 - Solid Colour PRODUCT CODE: PL 17

(Smooth, highly durable 2-pack polyurethane gloss enamel)

COLOUR: White only.

ENVIRONMENT: The Maintenance Cycle is a guide but can vary due to micro-climate changes identified on

the site which will affect the longevity of the coating system

As per ISO 12944: Maintenance Cycle (Years)

 C1 Inland
 10

 C3 Industrial
 10

 C5 Coastal / Marine
 10

Plascon Coating System	Application Method	Spreading Rate	WFT/DFT μm	Reducer/ Cleaner	Overcoating time	Technical Data Sheet	TVOC g/€
		m²/ℓ	(min & max)		h @ 23 °C	No	
Primer	B, R or S	@ 45 μm	WFT 100 -125	EPT 2	4	PEX 40	394
Plascoguard 40		Theo: 8.9	DFT 40-50				
Universal Epoxy		Prac: 5.2					
Primer							
(PEX 40/PEH 40)							
Mixing ratio:							
4:1 by volume							
1st Finishing Coat	B, R, S	@ 30 μm	WFT 69- 97	Glatex 8	16	PL	365 white
Plascon Glatex 8		Theo: 12	DFT 25-35	Thinner			
(PL 17)		Prac: 6.6		(PT 1)			
Mixing ratio							
3:1 by volume							
2 nd Finishing Coat	B, R, S	@ 30 μm	WFT 69- 97	Glatex 8	16	PL	365 white
Plascon Glatex 8		Theo: 12	DFT 25-35	Thinner			
(PL 17)		Prac: 6,6		(PT 1)			
Mixing ratio							
3:1 by volume							



Revision Date: January 2016



SPECIFICATION SHEET NO: NW403

SURFACE PREPARATION:

- Machine sand floors in direction of the grain to remove surface coatings or contaminants until a smooth and uniformly clean profile is obtained.
- ^ Rake out open joints to remove dirt and wax polish contaminants. Vacuum floor.
- Just before coating, wipe surface with mutton cloth dampened with Universal Reducer (PUR 1) to ensure a spotlessly clean and dust free surface.

APPLICATION:

Primer Coat

Mix base and hardener thoroughly in a 4:1 ratio by volume before use.

Apply one coat of Plascoguard 40 Universal Epoxy Primer (PEX 40/PEH 40) to achieve a continuous film. Allow 4 hours to dry.

Finishing Coats

Mixing:

Mix base and hardener thoroughly in a 3:1 ratio by volume before use.

Do not thin more that 5% with PT 1 Thinner.

Apply two full coats of Plascon Glatex 8 (PL 17) to achieve complete obliteration, allowing 16 hours drying between coats.

TABLE REFERENCES:

- Technical Data Sheet (TDS): User must always ensure that latest issue is used.
- B = Brush (ready for use), R = Roller (synthetic, min. 10mm pile) (ready for use), S = Airless spray (ready for use).
- Theoretical spreading rate quoted is for smooth non-porous substrates and does not include allowance for surface profile, porosity, wastage and uneven film application. Suitable allowance should be made according to type of work, method and skill of applicator. Practical spreading rate quoted is an average guide only - actual must be determined by user.
- ^ Overcoating times are at 23 °C and 75 % relative humidity. Longer times must be allowed under cooler and moist conditions. DO NOT paint during inclement weather and when temperature is below 10 °C.
- ^ Fading and chalking will occur to a greater or lesser degree depending on pigmentation and generic binder type.
- ^ NB: Life expectancy may vary, depending on environmental conditions and stresses, within the macro/micro climate of the project.

Copyright @Kansai Plascon (Pty) Ltd 2013. All rights reserved. No part of this work may in any form or by any means be reproduced without prior written permission of the copyright owner. PLASCON is the registered trade mark of Kansai Plascon (Pty) Ltd,

(-7), ---,



Revision Date: January 2016