

SPECIFICATION NO: NW293

\_\_\_\_\_

**NEW WORK/REPAINT:** NEW WORK – INTERIOR / EXTERIOR

**SUBSTRATE:** Cast Iron / Wrought Iron

PAINT FINISH: Plascon Silvershine Aluminium Paint PRODUCT CODE: ASS1

(Highly durable bright aluminium finish)

COLOUR: Silver

**ENVIRONMENT:** The Maintenance Cycle is a guide but can vary due to micro-climate changes identified on

the site which will affect the longevity of the coating system

As per ISO 12944-2:1998 Maintenance Cycle (Years)

 C1 Inland
 2

 C3 Industrial
 2

 C5 Coastal / Marine
 2

Plascon Coating	Application	Spreading	WFT/DFT	Reducer/	Overcoating	Technical	TVOC
System	Method	Rate	μm	Cleaner	time	Data Sheet	g/€
		m²/ℓ	(min & max)		h @ 23 °C	No	
Primer	B, R or S	@ 17.5 μm	WFT 76-192	PA-10	1	BPA 410	645
Plascon		Theo: 7.4	DFT 10-25	Thinner			
Plascoprime		Prac: 3.6		(CTH 5)			
PA-10							
(BPA 410)							
1 <sup>st</sup> Finishing Coat	B, R or S	@ 20 μm	WFT 27-45	Min.	16	ASS 1	336
Plascon		Theo: 28	DFT 15-25	Turps			
Silvershine		Prac: 14		(AZH 1)			
Aluminium Paint							
(ASS 1)							
2 <sup>nd</sup> Finishing Coat	B, R or S	@ 20 μm	WFT 27-45	Min.	16	ASS 1	336
Plascon		Theo: 28	DFT 15-25	Turps			
Silvershine		Prac: 14		(AZH 1)			
Aluminium Paint							
(ASS 1)							



Revision Date: January 2016



SPECIFICATION NO: NW293

## **SURFACE PREPARATION:**

^ Surfaces must be clean, dry and rust free. Remove surface contaminants using Plascon Metalcare Aquasolv Degreaser (GR 1), scrubbing with bristle brush or broom, or using Scotch Brite pads. Rinse thoroughly with tap water while brushing or hydroblast to remove all traces of Plascon Metalcare Aquasolv Degreaser (GR 1) to achieve a water break-free surface. Dry surface rapidly to prevent flash rust formation. Cleaned surface must be painted within 4 hours.

^ After degreasing sand off rust with coarse emery paper or wire brush to ISO 8501 - 01 : 2007 – St 3. Remove dust.

## **APPLICATION:**

## **Primer Coat**

Apply one coat of Plascon Plascoprime PA -10 (BPA 410) to entire substrate. For spray application thin with a minimum amount of PA-10 Thinner, not to exceed 20 % by volume. Allow 1 hour to dry.

## **Finishing Coats**

Apply two full coats of Plascon Silvershine Aluminium Paint (ASS 1) to achieve complete obliteration, allowing 16 hours drying between coats.

**TABLE REFERENCES:** 

- ^ Technical Data Sheet (TDS): User must always ensure that latest issue is used.
- B = Brush (ready for use), R = Roller (synthetic, min. 10mm pile) (ready for use), S = Airless spray (ready for use).
- ^ Theoretical spreading rate quoted is for smooth non-porous substrates and does not include allowance for surface profile, porosity, wastage and uneven film application. Suitable allowance should be made according to type of work, method and skill of applicator. Practical spreading rate quoted is an average guide only actual must be determined by user.
- ^ Overcoating times are at 23 °C and 75 % relative humidity. Longer times must be allowed under cooler and moist conditions. DO NOT paint during inclement weather and when temperature is below 10 °C.
- ^ Fading and chalking will occur to a greater or lesser degree depending on pigmentation and generic binder type.
- ^ NB: Life expectancy may vary, depending on environmental conditions and stresses, within the macro/micro climate of the project.

Copyright @Kansai Plascon (Pty) Ltd 2013. All rights reserved. No part of this work may in any form or by any means be reproduced without prior written permission of the copyright owner. PLASCON is the registered trade mark of Kansai Plascon (Pty) Ltd,



Revision Date: January 2016